

## Bill of Materials

Reference	Qty	Part Number	Description	Package	Manufacture
U1	1	RT4730WSC	DC-DC Converter	WL-CSP-16B 2.34x2.34 (BSC)	RICHTEK
C1	1	C1608X5R1E475KT000E	4.7μF/25V/X5R	0603	TDK
C2	1	0603X105K250CT	1μF/25V/X5R	0603	WALSIN
C3, C5, C17	4	0603X106M6R3CT	10μF/6.3V/X5R	0603	WALSIN
C4, C6	2	0603X475K6R3CT	4.7μF/6.3V/X5R	0603	Murata
C7, C15	5	JMK107BBJ226MA-T	22μF/6.3V/X5R	0603	TAIYO YUDEN
C8	1	0603B104K500CT	0.1μF/50V/X5R	0603	WALSN
C9, C10, C11, C12, C13, C14, C16	8	NC	NC	0603	
L1	1	1269AS-H-2R2M	2.2μH	2.5x2.0x1.0mm	Murata
L2	1	1269AS-H-2R2M=P2	2.2μH	2520	Murata
R1	1	WR06X000 PTL	0	0603	WALSIN
R2, R3, R6, R7, R8	5	NC	NC	0603	
R4, R5	2	WR06X4701FTL	4.7k	0603	WALSIN
CP1, CP2	2		Short	0603	

## More Information

For more information, please find the related datasheet or application notes from Richtek website <http://www.richtek.com>.

## Important Notice for Richtek Evaluation Board

THIS DOCUMENT IS FOR REFERENCE ONLY, NOTHING CONTAINED IN THIS DOCUMENT SHALL BE CONSTRUED AS RICHTEK'S WARRANTY, EXPRESS OR IMPLIED, UNDER CONTRACT, TORT OR STATUTORY, WITH RESPECT TO THE PRESENTATION HEREIN. IN NO EVENT SHALL RICHTEK BE LIABLE TO BUYER OR USER FOR ANY AND ALL DAMAGES INCLUDING WITHOUT LIMITATION TO DIRECT, INDIRECT, SPECIAL, PUNITIVE OR CONSEQUENTIAL DAMAGES.