



| Symbol | Dimensions In Millimeters | | Dimensions In Inches | |
|--------|---------------------------|-------|----------------------|-------|
| | Min. | Max. | Min. | Max. |
| A | 3.600 | 4.320 | 0.142 | 0.170 |
| A1 | 0.381 | 0.710 | 0.015 | 0.028 |
| A2 | 3.000 | 3.600 | 0.118 | 0.142 |
| b | 0.360 | 0.560 | 0.014 | 0.022 |
| b1 | 1.143 | 1.778 | 0.045 | 0.070 |
| D | 9.050 | 9.550 | 0.356 | 0.376 |
| E | 6.200 | 6.600 | 0.244 | 0.260 |
| E1 | 7.620 | 8.255 | 0.300 | 0.325 |
| e | 2.540 | | 0.100 | |
| L | 3.000 | 3.600 | 0.118 | 0.142 |