



Symbol	Dimensions In Millimeters		Dimensions In Inches	
	Min.	Max.	Min.	Max.
A	0.500	0.600	0.020	0.024
A1	0.000	0.050	0.000	0.002
A3	0.100	0.200	0.004	0.008
D	4.900	5.100	0.193	0.201
E	3.900	4.100	0.154	0.161
b (x32)	0.150	0.250	0.006	0.010
b1 (x2)	0.290	0.390	0.011	0.015
L (x28)	0.280	0.380	0.011	0.015
L1 (x2)	0.800	0.900	0.031	0.035
L2 (x2)	2.050	2.150	0.081	0.085
L3 (x2)	0.690	0.790	0.027	0.031
e	0.420		0.017	
e1	0.700		0.028	
e2	0.723		0.028	
e3	0.706		0.028	
e4	0.560		0.022	
e5	0.490		0.019	
e6	1.540		0.061	
K	0.325		0.013	
K1	1.016		0.040	
K2	1.148		0.045	
K3	1.360		0.054	